

SONY.

Hi-Fi Products
Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MDS-501

No. 431

Subject: Level Meter Reading Without Input Signal

Date: March 16, 1995

Symptom:
(**)

While in the analog record mode, with no input signal, the lower segments of the peak meter will light after a while.

Solution: Replace System Control, IC301. IC301 is located on the Display board.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
IC301	M38197MA-071FP	8-759-259-15	M38197MA-076FP	8-759-278-73

Applicable Serial Number Range:
805100 and Later.

