

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: MHC GENERAL

No. 434


Subject: Static Noise during Playback

Date: March 20, 1995

Symptom:

(**) A static noise is heard when playing back a tape.

Solution: Replace the motor assembly (capstan) as listed below.



Applicable Models:

TC-H7900

DXA-C70/C90

HCD-H61M



Filename: HFP0434.SB
Directory: J:\SBDOC\MAR95
Template: C:\WINWORD\S_BULL.DOT
Title: MHC/Gen
Subject:
Author: Hoyt Wing Lee
Keywords:
Comments:
Creation Date: 03/20/95 10:09 AM
Revision Number: 2
Last Saved On: 03/20/95 10:09 AM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 1 Minute
Last Printed On: 04/01/96 9:31 AM
As of Last Complete Printing
Number of Pages: 2
Number of Words: 105 (approx.)
Number of Characters: 604 (approx.)