

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: HCD-H51M

No. 440

Subject: Part number correction

Date: May 25, 1995


Symptom:

(**)

Please note the following part number correction.

Solution:

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
11	13 PIN FLEX CABLE	1-690-970-31	1-751-042-31



Filename: HFP0440.SB
Directory: J:\SBDOC\MAY95
Template: C:\WINWORD\TEMPLATE\S_BULL.DOT
Title:
Subject:
Author:
Keywords:
Comments:
Creation Date: 05/25/95 8:45 AM
Revision Number: 3
Last Saved On: 05/25/95 8:46 AM
Last Saved By: Hoyt Wing Lee
Total Editing Time: 1 Minute
Last Printed On: 04/01/96 9:48 AM
As of Last Complete Printing
Number of Pages: 3
Number of Words: 100 (approx.)
Number of Characters: 572 (approx.)