Hi-Fi Products Service Bulletin

Sony Service Company - Technical Services A Division of Sony Electronics Inc. Sony Drive, Park Ridge, New Jersey 07656

Model: MHC-450, HCD-H450/H450M No. 449

Subject: Extension Cable Availability **Date:** September 13, 1995


Symptom:


(**) Troubleshooting is difficult without an extension cable.

Solution: A 23p Extension cable is now available for servicing this unit while it is

disassembled. The part number for the cable Is J-2501-087-A. It is used to connect CN201 of the Main board to CN101 of the BD board. See diagram

below.





Autoflagged - NO



Audio Products Service Bulletin No. xxx

Filename: HFP0449.SB

Directory: J:\SBDOC\SEP95

 $C: \verb|VINWORD| TEMPLATE | S_BULL.DOT$ Template:

Title: Subject:

Hoyt Wing Lee Author:

Keywords: Comments:

Creation Date: 09/13/95 11:17 AM

Revision Number:

Last Saved On: 09/13/95 11:17 AM Last Saved By: Hoyt Wing Lee Total Editing Time: 0 Minutes

Last Printed On: 04/01/96 11:03 AM

As of Last Complete Printing Number of Pages: 2

Number of Words: 124 (approx.)

707 (approx.) Number of Characters: