

Hi-Fi Products Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: HCD-H305, HCD-H405, HCD-H605, MHC-C305, MHC-C405, MHC-C605, MHC-C33, MHC-C55 **No. 459R1**

Subject: TRAY JAMS **Date:** February 15, 1996

Symptom:
(161) The tray may jam due to the tray ass'y and stocker(Ref # 332) being out of position. This causes the sub tray to be released from the hook.

Solution: Attach a spacer and a rubber cushion in order to fasten the stocker.

Ref.	Description	Part No.
1	SPACER	4-977-341-01
2	RUBBER CUSHION	4-973-608-01

