

# Hi-Fi Products Service Bulletin

**CSA-13**

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** HCD-D560

**No.** 463

**Subject:** Part Number Correction - Reference No. F1903, Fuse  
**Date:** January 16, 1996

**Symptom:**

(\*\*)

The part number listed on page 27 (Schematic) & page 99 (Parts List) of the Service Manual for Ref # F1903, Fuse (3.15A, 125V), is incorrect.

**Solution:**

When an HCD-D560 (LBT-D560) is in for service, for any reason, verify that F1903 is 4A, 125V. If not, please replace it with the correct part number below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
F1903	FUSE	1-576-107-11	1-576-108-11

