

Hi-Fi Products

Service Bulletin

CSA-13

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: GENERAL

No. 466

Subject: CD Mechanism Alignment Video Available

Date: January 31, 1996

Symptom:

(**)

The CD mechanism alignment procedure for the MHC-C305 ,MHC-C33 and the CFD-606/616/and 626 is not available in the Service manual.

Solution:

A video tape showing the disassembly and alignment of the MHC-C305, MHC-C33 CFD-606/616, and 626 CD mechanisms is now available through Kansas City Parts. The part number for this video tape is: **T-CDMECH1-96**.

Requests Should be mailed to :

Sony Service Company
Attn: Publications Department
National Parts Center
P.O. Box 20407
Kansas City ,MO 64195

