

**Model:** STR-D965**No.** 501**Subject:** Erased Memory**Date:** December 4, 1996**Symptom:**

(\*\*)

The customer complaint may state, when the surround level is set to maximum and the unit is powered off, all memory is erased.

**Solution:** Replace the part listed below.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
IC104	MB90673-144	8-759-384-77	MB90P673-144	8-759-451-99

