

**Model:** D-515

**No.** 507

**Subject:** Substitution for IC504 (DC/DC Converter)

**Date:** January 13, 1997

**Symptom:**

(\*\*\*) Production of the MPC1716AFU has stopped.

**Solution:**

Use the MPC1718FU and remove the components listed below.

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
IC504	MPC1716AFU	8-759-039-13	MPC1718FU	8-759-084-72
R546	4.7K 1/16W RESISTOR	1-216-829-11	REMOVE	
R580	10K 1/16W RESISTOR	1-216-833-11	REMOVE	
C591	10UF 6.3V TANTALUM CAP	1-135-259-11	REMOVE	
C555	.001UF 50V CAP	1-164-473-11	REMOVE	

