

Model: D-242CK, D-245**No.** 510**Subject:** IC 501 (RF amp) No longer Available**Date:** January 30, 1997**Symptom:****(***)**

IC 501 (BA6375K) is no longer available. When replacing this component, use the IC identified below.

Solution:

REF	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
IC501	BA6375K	8-759-325-52	BA6376K	8-759-335-59

