

Sony Service Company National Technical Services A Division of Sony Electronics Inc. Park Ridge, New Jersey 07656

CONFIDENTIAL

Service Bulletin Hi Fi Products



Model: D-335

No. 512

Subject: Abnormal LCD Display and / or No Key Input

Date: January 30, 1997

Symptom:

(**) Abnormal LCD Display and / or No Key Input accepted Applicable Serial Numbers (100,001 ~ 251,510)

Solution: 1. File the pattern of the power supply and clean it with alcohol (See fig 1.)

2. Place Rubber cushion on top of the DC in Jack (Fig. 2)

Confirm continuity between the screw in the upper lid and the Negative (-) terminal of the Battery

REF	DESCRIPTION	PART NUMBER
	RUBBER CUSHION	3-355-463-01



