

Model: D-311**No.** 515**Subject:** IC 504 (PWM Driver) No Longer Available.**Date:** January 28, 1997**Symptom:****(***)**

The PWM driver is no longer available

Solution:

When replacing the IC, use the chip defined below.

| REF | FORMER | | NEW | |
|-------|-------------|--------------|------------------|--------------|
| | DESCRIPTION | PART NUMBER | DESCRIPTION | PART NUMBER |
| IC504 | MPC1716FU | 8-759-039-13 | MPC1718FU | 8-759-084-72 |

