

Model: D-824K**No.** 517**Subject:** Part Number Correction - Reference No. IC502,
BU9310BKS**Date:** February 11, 1997**Symptom:**

(**)

The part number listed on page 29 of Revised Service Manual for Ref # IC502,
BU9310BKS, is incorrect.**Solution:**

Please note the correct part number as shown below.

REF	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
IC502	BU9310BKS	8-759-193-61	8-759-293-61

