

Model: SDP-EP9ES**No.** **524****Subject:** Audible Noise When Volume Level Changed**Date:** March 28, 1997**Symptom:****(254)**

The customer may complain of noise when raising or lowering the volume control.

Solution:

Add a 33mF/10V capacitor in parallel with R698,R701, R704, R707, R710 and R713 on the TR Board.

REF	DESCRIPTION	PART NUMBER
N/A	33MF/10V CAPACITOR	1-124-229-00

Applicable Serial Number Range: 800001 - 801500

