



Sony Service Company  
National Technical Services  
A Division of Sony Electronics Inc.  
Park Ridge, New Jersey 07656

# CONFIDENTIAL

## Service Bulletin

### HIFI Products

**CSA-13**

**Model:** D-151, D-340, D-152, D-153, D-345

**No. 531**

**Subject:** Sound Skipping

**Date:** June 12, 1997

**Symptom:**  
(157) Sound Skipping

**Solution:** Too much room around the feed screw of the optical pick-up. Replace the sled spring with the improved one.

DESCRIPTION	PART NUMBER
SLED SPRING	4-972-163-04

