SONY®

## Hi-Fi Products Service Bulletin



**Sony Service Company -** Technical Services A Division of Sony Electronics Inc. Sony Drive, Park Ridge, New Jersey 07656

Model: CDP-C75ES/C85ES/C705 No. 270

**Subject:** Part Number Missing - Frame **Date:** October 11, 1993

Symptom:

(\*\*) The part number for the frame, which is shown on page 33 of the Service Manual, is

not listed in the parts list.

**Solution:** Please add the following part number to the Service Manual.

| REF | DESCRIPTION | PART NUMBER  |
|-----|-------------|--------------|
| _   | FRAME       | 4-924-407-09 |

Audio Products Service Bulletin No. xxx

## **Service Bulletin Check-Off Form**

Originator: ..... Larry Redner

Diagram Location: . cdp-c75es s/m

| PERSON     | ACTIVITY             | INITIAL | DATE | COMMENTS |
|------------|----------------------|---------|------|----------|
| Originator | Draft Creation       |         |      |          |
| Wing       | Drawings & Numbering |         |      |          |
| Originator | Proofing             |         |      |          |
| Manager    | Approval             |         |      |          |
|            | Notify KCP           |         |      |          |
|            | AutoFlagging         |         |      |          |
| Wing       | Distribution         |         |      |          |
| Jayne      | SDIS Entry           |         |      |          |