

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: STR-D159, LBT-D220**No.** 371R1**Subject:** Loss of tuner preset memory**Date:** February 28, 1994**Symptom:****(21)**

The tuners preset memory may be lost when the power is turned off after turning the volume up and down several times with the remote commander.

Solution:

Add a 10K resistor to pin 9 of IC601. IC601 is located on the panel board. See diagram below.



Service Bulletin Check-Off Form

Originator: Engineer Name

Diagram Location: .

PERSON	ACTIVITY	INITIAL	DATE	COMMENTS
Originator	Draft Creation			
Wing	Drawings & Numbering			
Originator	Proofing			
Manager	Approval			
	Notify KCP			
	AutoFlagging			
Wing	Distribution			
Rob	SDIS Entry			