

SONY car stereo

Service Bulletin No.57

CONSUMER SERVICE COMPANY
Technical Department

Model: XR-15

Date: March 19, 1986

Subject: Service Manual Correction,
Front-End Block Wiring

Note the correct wiring diagram for the front-end block on page 16 of the service manual.

