

SONY

car stereo Service Bulletin No.66

Technical Department
Sony Service Company
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-787R (CONNECTION WITH CDX-5)

Date: July 31, 1986


Subject: Instruction Manual Correction

Symptom:
(**)

Note the connections in the hook-up diagram for the XR-787R and CDX-5.

4-SPEAKER CONNECTION—with a Sony compact disc player such as the CDX-5

With the compact disc player connected to the XR-787R as illustrated, the CD sound can be heard without an add-on power amplifier.



Also note when the XR-787R and CDX-5 are connected together. Radio ON/OFF switch on the XR-787R must be OFF in order to use the tape deck or the CDX-5.

If the radio is ON, the tape deck and the CDX-5 will not function.