

SONY

Car Stereo
Service Bulletin

Sony Service Company - Technical Services
A Division of Sony Corporation of America
Sony Drive, Park Ridge, New Jersey 07656

Model: XR-U550

No. 258

Subject: Part Number Correction: Sub-panel (Ref. 1)

Date: September 17, 1992


Symptom:
(**)

The part number shown in the Service Manual for the sub-panel (Ref. 1) is incorrect.

Solution:

Please make the following correction to your Service Manual:

REFERENCE	DESCRIPTION	PART NUMBER	
		INCORRECT	CORRECT
1	PANEL, SUB (U550)	3-377-596-01	3-377-595-01



CSA-14 Tuner/Tape Deck