

Model: CPD-15SF2, CPD-100SF, CPD-100VS**No.** 185**Subject:** FBT Anode Lead Part Number**Date:** March 4, 1998**Symptom:****(***)**

If the Flyback Transformer, T501 (PN X-403-308-31) is replaced, the replacement part does not include the Anode Lead assembly for the CRT. The original anode lead assembly should not be used again.

Solution:

Then, please use the following part number to order an anode lead assembly to use with the replacement flyback transformer.

REF	DESCRIPTION	PART NUMBER
NA	FBT ANODE LEAD	1-540-005-21

Please add this part number to the parts list in the Service Manual.