

**Model:** CPD-15SF2, CPD-17SF2**No.** 142**Subject:** OSD Missing or Displayed Incorrectly**Date:** January 6, 1997**Symptom:****(122)**

If the On Screen Display (OSD) is not showing or is displayed incorrectly. This occurs especially when the Input Video Vert. Freq. is 99.5 -100 Hz. This may be caused by CPU IC901 on the D Board.

**Solution:**

Then please replace IC901 on the D Board. Refer to illustration shown below.

NOTE : The part listed below is needed to complete this procedure.

MODEL	REF	DESCRIPTION	PART NUMBER
CPD-15SF2	IC901	IC ST7271N5B1/CCM	8-759-354-66
CPD-17SF2	IC901	IC ST7271N5B1/CER	8-759-370-67

**IC901 LOCATION**