

# SONY®

## Service Bulletin

NO:ME2-00-004

---

**SUBJECT:** INTRODUCTION OF FRONT PANEL JIG

---

**DATE:** MAY 2000

**MODEL (S):** CDX-C8850, MDX-C8900, MDX-C8970

---

**Symptom:** The extension cable for the front panel to the main unit has been supplied under the following part number

**Solution:** Order the Extension Jig below.

| DESCRIPTION                | PART NUMBER  |
|----------------------------|--------------|
| EXTENSION CABLE, KEY MOUNT | J-2502-052-1 |