

# SONY® Service Bulletin

NO: ME3-97-003


SUBJECT: PART NUMBER INFO: MOUNTING HARDWARE

DATE: AUGUST 1997

MODEL (S): MDX-40

On page 36 of the Service Manual, part #501 and #502 are reversed. Please correct the Service Manual as follows: #501 corresponds to **Bracket Assy (X-3368-710-1)** and #502 corresponds to **Bracket Assy (A) (3-915-870-01)**.

## MOUNTING HARDWARE



<del>502</del>	<del>✗</del>	3-915-870-01 BRACKET (A)
<del>501</del>	<del>✗</del>	X-3368-710-1 BRACKET ASSY
503		4-304-511-00 NUT (M5), FLANGE
504		3-915-871-01 CAP
505		7-621-559-63 SCREW +K 2.6X10
506		3-913-873-01 CUSHION (COVER)

ME03096