

SONY®

Service Bulletin

NO:HIFI2-98-001

SUBJECT: REPLACEMENT LITHIUM BATTERY AVAILABLE

DATE: JUNE 1998

MODEL (S): MZ-R2

Symptom: A replacement Lithium battery is available from WRPC-AS.

Solution: Use part number 1-528-330-11 when ordering.

Note: before installing the new battery bend the positive and negative terminals to match the configuration of the original battery.

PART
SONAM464

Sony of Canada Ltd.

115 Gordon Baker Road, Willowdale, Ontario M2H-3R6
NATIONAL LAB - CONSUMER SERVICE