

# SONY® Service Bulletin

NO: HIFI2-99-013

---

**SUBJECT: USING 80 MINUTE MINIDISCS FOR RECORDING**

---

**DATE: AUGUST 1999**

**MODEL (S): MDS-S38**

---

**SYMPTOM:** The Customer complaint states when recording on an 80 minute Mini disc the maximum recording indicator does not beep.

**SOLUTION:** This is normal, a recording can be made for the maximum of 80 minutes in Stereo and 160 minutes in Mono.

SONAM 597  
AU99011

Sony of Canada Ltd.

115 Gordon Baker Road, Toronto, Ontario M2H-3R6  
NATIONAL LAB - CONSUMER SERVICE