

Repair tips

SUBJECT: Unit shows a 138 error at the end of auto alignment.

DATE: 05/13/2002

MODEL (S): MZ-R500,R700,R900, Gen MZ-R,

Symptom: Unit shows a 138 error at the end of auto alignment.

Solution: This error means that the erase head was unable to affect the recording track and the track is 'Blank', totally unrecorded after the record test:

This can be due to record head misalignment, no record drive, cut record head wiring or any other problem that prevents the record magnet from affecting the disk.

Submitted By: Brian @ PHD Electronics Ltd.

Sony of Canada Ltd.

115 Gordon Baker Road, Toronto, Ontario M2H-3R6
NATIONAL LAB - AVIT