

Repair tips

SUBJECT: Error code 131 or 132

DATE: 06/22/2002

MODEL (S): MZ-R70, R90, R500, R700, R900

Symptom: Error code 131 or 132: The code means the unit cannot place the optic on the track it wants.

Solutions: Spindle motor is not spinning right or a stuck sled drive: Replace Spindle motor.

Submitted By: PHD Electronics Ltd

Sony of Canada Ltd.

115 Gordon Baker Road, Toronto, Ontario M2H-3R6
NATIONAL LAB - AVIT