

Model: CPD-200ES**No.** 200R1**Subject:** New Cabinet Parts for Units with CRT Shield**Date:** September 8, 1998**Symptom:**
(1161)

Some of the replacement parts for the cabinet were changed on units built with the CRT EMI Shield added. Affected SN range is above 4120001.

Solution:

Please use the following part numbers to order replacement parts for the cabinet on units with the CRT shield.

PARTS FOR UNITS WITH CRT SHIELD

REF	DESCRIPTION	PART NUMBER
1	Bezel Assy	X-4035-766-1
25	Bottom Cover	4-066-857-01
31	Cabinet Assembly	X-4035-767-1
NA	Screw Cover	4-066-919-01

Please use the following part numbers to order replacement parts for the cabinet on units without the CRT shield

PARTS FOR UNITS WITHOUT CRT SHIELD

REF	DESCRIPTION	PART NUMBER
1	Bezel Assy	X-4034-876-1
25	Bottom Cover	4-060-612-01
31	Cabinet Assembly	X-4034-877-1
NA	Screw Cover	4-060-165-11

Please maintain this Service Bulletin with the service manual.