

# Computer Monitors Service Bulletin

CSI-111

Sony Service Company - Technical Services  
A Division of Sony Electronics Inc.  
Sony Drive, Park Ridge, New Jersey 07656

**Model:** GDM17SE1

**No. 76**

**Subject:** Countermeasure for High Pitch Squeal

**Date:** January 9, 1995

**Symptom:**

**(154)**

A high frequency squeal is audible when using the MAC 16" Mode

**Solution:**

The noise comes from JW097 (jumper wire). JW097 vibrates due to L501 (Horizontal Linearity Coil). To confirm the noise source, touch the center of JW097 using a plastic adjustment tool.

If the Noise is confirmed, apply RTV in the middle of the jumper wire as illustrated below:

JW097 is located in the middle of the D-Board near L501 and T502.



