

Computer Monitors Service Bulletin

CSI-111

Sony Service Company - Technical Services
A Division of Sony Electronics Inc.
Sony Drive, Park Ridge, New Jersey 07656

Model: GDM17SE1, GDM20SE1

No. 75

Subject: Countermeasure for high pitch squeal

Date: January 9, 1995

Symptom:

(154) High Pitch Squeal noise

Solution:

In some cases a high pitch squeal may be emitted by L501 and/or L507 on the D-Board. Please change to the new part respectively.

DESCRIPTION	OLD PART NUMBER	NEW PART NUMBER
L501 FOR THE 17"	1-409-597-11	1-409-599-11
L501 FOR THE 20"		1-409-690-11
L507 FOR THE 17"	1-409-598-11	1-460-080-12
L507 FOR THE 20"		1-409-691-11



