

Date 16.07.99	Ref. No. IP00499	Model CMD-C1	DT
Subject Plug for Cigar Lighter Charger (QN-C1CC)			IRIS

SYMPTOM

In some motor vehicles it may happen that the power supply plug of the cigar lighter charger moves a little bit during driving when it is connected to the cigar lighter. As a result the power supply may be interrupted occasionally.

SOLUTION

To solve this exceptional problem on some car brands, a 'Distance Adapter' has been provided to realize a perfect fitting.

1. The 'Distance Adapter' is available through DTCE Office, Service Promotion in Munich.
2. If needed, the 'Distance Adapter' will be provided free of charge.