
Model: CCD-TR2300, CCD-TR330, CCD-TR3300, CCD-TR416, CCD-TR44, CCD-TR440, CCD-TR46, CCD-TR514, CCD-TR516, CCD-TR54, CCD-TR614, CCD-TR64, CCD-TR67, CCD-TR710, CCD-TR714, CCD-TR716, CCD-TR74, CCD-TR78, CCD-TR814, CCD-TR84, CCD-TR87, CCD-TR88, CCD-TR910, CCD-TR917, CCD-TR94, CCD-TR940, CCD-TR98, CCD-TR99, CCD-TRV11, CCD-TRV119, CCD-TRV15, CCD-TRV16, CCD-TRV19, CCD-TRV21, CCD-TRV211, CCD-TRV215, CCD-TRV25, CCD-TRV29, CCD-TRV31, CCD-TRV36, CCD-TRV41, CCD-TRV43, CCD-TRV51, CCD-TRV615, CCD-TRV65, CCD-TRV66, CCD-TRV715, CCD-TRV75, CCD-TRV81, CCD-TRV815, CCD-TRV85, CCD-TRV93, CCD-TRV95, CCD-TRV99, DCR-TR7000, DCR-TRV103, DCR-TRV110, DCR-TRV310, DCR-TRV315, DCR-TRV510, **No. 503**

Subject: B Mech general information - See "GEN-CAM". **Date:** September 7, 1999

Symptom:
(1170)

All general information that applies to a common Camcorder mechanism will now be listed under model "GEN-CAM". Additional key word searches may be performed to narrow the search to a specific mechanism.

Solution:

For example, to find all general B mechanism service bulletins and FPR's, search under model "GEN-CAM" and search the subject for "B-Mech".