

Model: DCR-TRV310, DCR-TRV315, DCR-TRV510**No.** 505**Subject:** Cabinet (R) Key Switch Failure**Date:** November 2, 1999**Symptom:****(****)** Some key switches may fail (remain depressed).**Solution:** Replace the Cabinet-R Assy with the improved one.

MODEL	FORMER		NEW	
	DESCRIPTION	PART NUMBER	DESCRIPTION	PART NUMBER
DCR-TRV310/ 315	CABINET (R) ASSY	X-3949-449-1	CABINET (R) ASSY	X-3949-449-5
DCR-TRV510	CABINET (R) ASSY	X-3949-494-1	CABINET (R) ASSY	X-3949-494-4