## SR720 s/n 15682 Modification

This model SR720 has had a special modification which reduces the applied voltage to the part under test. Because of this modification the error message "drv Err 6" will occur during self test at startup. This error message should be disregarded and cleared by pressing any button.

The amplitudes of the applied voltages on this unit are:

| Vset (mV)                  | Vactual (mV)          |
|----------------------------|-----------------------|
| 250<br>200*<br>150*<br>100 | 112<br>89<br>67<br>50 |
|                            |                       |

\* These two settings are accessable only throught the "cal" menu of the instrument.

Stanford Research Systems May 16, 1996