

# PRODUCT DISCONTINUANCE BULLETIN



**Issue Date:** April 1, 2005

**PDB Number:** PDB\_6530.Doc

## Product

Symmetricom Model 6530A Fiber Optic Distribution Transmitter

## Overview

Symmetricom is announcing the discontinuance of the Symmetricom Model 6530A Fiber Optic Distribution Transmitter. The 6530A has reached the end of its technology product lifecycle and is being discontinued. There is no direct replacement for this product but similar functionality is available with the Symmetricom 56000 modular distribution system. There are 18 units available for sale. There will be no additional units manufactured after the 18 units are depleted.

## Product Obsolescence Timeline

Milestone	Date
Last Day to Order	October 1, 2005

## Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement Datasheet Link
6530A	14430-101 14430-102 14430-103 14430-104	None	None	

## Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available on a best efforts basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

## Contact Information

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide  
support@symmetricom.com  
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.  
Santa Rosa, CA 95403  
Telephone: 707-528-1230  
Facsimile: 707-527-6640