

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: April 1, 2005

PDB Number: PDB_6531.Doc

Product

Symmetricom Model 6531A Fiber Optic Distribution Receiver

Overview

Symmetricom is announcing the discontinuance of the Symmetricom Model 6531A Fiber Optic Distribution Receiver. The 6531A has reached the end of its technology product lifecycle and is being discontinued. There is no direct replacement for this product but similar functionality is available with the Symmetricom 56000 modular distribution system. There are 13 units available for sale. There will be no additional units manufactured after the 13 units are depleted.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	October 1, 2005

Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement Datasheet Link
6531A	14331-101 14431-102 14431-103 14431-104	None	None	

Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available on a best efforts basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640