

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: August 18, 2003

PDB Number: PDB_4040B.Doc

Product

Symmetricom Model 4040B Cesium Frequency Standard



4040B



Cs4000

Overview

Symmetricom is announcing the discontinuance of the Symmetricom Model 4040B Cesium Frequency Standard. The 4040B is being replaced by the Cs4000. The Cs4000 offers improved frequency stability and frequency accuracy, multiple RF and Timing outputs, battery back-up, remote monitoring and control and a wide range of optional configurations.

Please go to <http://www.symmetricom.com/support/discontinuance> for detailed product information.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	November 18, 2003

Affected Models and Replacement Product Summary

Current Model	Current Part #	Replacement Model	Replacement Part #
Symmetricom Model 4040B Cesium Frequency Standard	4040B	Cs4000 Cesium Frequency Standard	Cs4000

Contact information.....

Support Policy

Product support services (telephone technical support, on-site maintenance, training, spares support, etc.) and repairs are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640