

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: July 14, 2003

PDB Number: PDB_4310A

Product

Symmetricom CsIII, Model 4310A Cesium Frequency Standard



4310A



4310B

Overview

Symmetricom is announcing the discontinuance of the Symmetricom CsIII, Model 4310A Cesium Frequency Standard. The 4310A is being replaced by the CsIII, Model 4310B. The 4310B offers improved frequency stability and frequency accuracy along with DC input voltage options and a new look front panel. All rear panel connectors and connector locations remain the same. Please go to <http://www.symmetricom.com/support/discontinuance> for detailed product information.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	August 14, 2003

Affected Models and Replacement Product Summary

Current Model	Current Part #	Replacement Model	Replacement Part #
Symmetricom Model 4310A Cesium Frequency Standard	4310A	4310B Cesium Frequency Standard	4310B

Support Policy

Contact information.....

Product support services (telephone technical support, on-site maintenance, training, spares support, etc.) and repairs are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640