PRODUCT DISCONTINUANCE BULLETIN



Issue Date: March 7, 2003 PDB #:PDB_D_9150-3059

Product

Datum Model 9150-3059 Airborne Time Code Generator

Overview

Symmetricom is announcing the discontinuance of the Datum Model 9150-3059 Airborne Time Code Generator. The 9150-3059 has reached the end of its technology product lifecycle and other, newer Symmetricom 700 Airborne Time Code Generator will replace this model.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	June 7, 2003
End of Customer Support/Repair Contracts date (i.e. no customer support contract can extend beyond this date)	June 7, 2004
Begin Best Effort Support/Repair date	June 7, 2004

Affected Models and Replacements

Current Model	Current Part #	Replacement Model	Replacement Part #	Replacement Datasheet Link
Datum 9150-3059 Airborne Time Code Generator	9150-3059	700 Series Airborne Time Code Generator	700-100	<u>Datasheet</u>

Support Policy

Technical support and product repair for the discontinued model will be on a best effort basis for as long as possible and at Symmetricom's discretion. There may be fees associated with support and repairs. Maintenance and extended warranty contracts are not available.

Contact Information

Symmetricom Global Services: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA

1-408-428-7907 worldwide support@symmetricom.com www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.

Santa Rosa, CA 95403 Telephone: 707-528-1230 Facsimile: 707-527-6640