

# PRODUCT DISCONTINUANCE BULLETIN



**Issue Date:** March 7, 2003

**PDB #:**PDB\_D\_bc420-427VXI.doc

## Product(s)

Datum Model bc420VXI RF Pulse Analyzer  
Datum Model bc427VXI GPS RF Pulse Analyzer

## Overview

Symmetricom is announcing the discontinuance of the Datum bc420/427VXI RF Pulse Analyzer. The bc420/427VXI has reached the end of its technology product lifecycle and the manufacturing of this product is being discontinued

## Product Obsolescence Timeline

Milestone	Date
Last Day to Order	June 7, 2003

## Affected Models and Replacement Product Summary

Current Model	Current Part #	Replacement Model
Datum Model bc420VXI RF Pulse Analyzer	BC420VXI	none
Datum Model bc427VXI GPS RF Pulse Analyzer	BC427VXI	

## Support Policy

Product support services (telephone technical support, on-site maintenance, training, spares support, etc.) and repairs are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. All services may not be available for every product. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

## Contact Information

Symmetricom Global Services 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide  
support@symmetricom.com  
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.  
Santa Rosa, CA 95403  
Telephone: 707-528-1230  
Facsimile: 707-527-6640