

Calibrator Accessories

TEMPERATURE CALIBRATORS

Calibration Kits

TEGAM Calibration Kits are what you need to calibrate temperature devices and check temperatures throughout your plant. No matter what sensor type or connection method, these kits let you calibrate and check temperature controllers, recorders, process monitors, panel meters and transmitters. The heart of each TEGAM Calibration Kit is the 800 Series handheld temperature calibrator (sold separately) that combines bench-meter performance with a data-logging thermometer. Take a look at everything that you get:



KIT #1

K, J, & T Universal Adaptor Kits – each adaptor kit contains a 3' calibration cable with spade lug terminals plus a standard connector and a subminiature connector.
 AC Adaptor/Battery Charger & Rechargeable Battery
 Rubber Boot & Belt Clip
 Type K Wire Temperature Sensor
 Foam-Filled Carrying Case



KIT #5

K, J, T & E Alligator Clip Calibration Cables
 4-Wire RTD/Ohms/Thermistor Alligator Clip Calibration Cable
 2 RTD 4-Pin Connectors
 AC Adaptor/Battery Charger & Rechargeable Battery
 Rubber Boot & Belt Clip
 Type K Wire Temperature Sensor
 Foam-Filled Carrying Case

NOTE: Calibration Kits should be ordered by Kit # along with the calibrator of your choice (not included).

High Impact Carrying Case (as shown in Kit 1 & 5 above)

This case has a foam insert for 840 and 850 Series Calibrators and 819 and 820 Series Thermometers.

ORDERING INFORMATION

MODEL 5000



Rubber Boot and Belt Clip

This rubber boot protects your instrument from everyday bangs and bumps in your toolbox. This boot is designed to protect your calibrator while not interfering with plugging in cables, using the tilt stand or the AC adaptor. Also included is a removable belt clip.

ORDERING INFORMATION

MODEL 8204

EXTENSION CABLES (Not shown)

MODEL NUMBER BY TC TYPE

K	INSULATION	LENGTH	CONNECTORS (Miniature TC)
80141	1PVC	3 ft	One Male and One Female

AC Adapter/Battery Charger & Rechargeable Battery: Used to recharge the battery when not in use or extend battery life during use. (no photo)

ORDER 80010 Adapter (Not Shown)

80010, 80010/100 or 80010/220 Adapter	MODEL NUMBERS
TYPE	840A, 845, 850, 855
Calibrators	



YOUR GLOBAL SOURCE FOR TEST AND MEASUREMENT SOLUTIONS

10 TEGAM WAY • GENEVA, OHIO 44041
 440-466-6100 • FAX 440-466-6110
 www.tegam.com • e-mail: sales@tegam.com