


# Calibration Procedures

**Model: CENTER 304 / 309**

Step	Function	Input Signal	Adjustment	Adjust Range	Remark
1.	0°C	0°C	VR1	-0.1~0.1°C	
2.	190°C	190°C	VR2	189.9~190.1°C	
3.	1000°C	1000°C	VR3	999~1001°C	
4.	1900°F	1900°F	VR4	1899~1901°F	



304-049 Mechanical Layer 2