


ORIGINATED BY *Mike Clegg*

MODEL OR MODULE AFFECTED

M 10 G / 10GA

NATURE AND REASON FOR CHANGE Change TORROID (L11) ground Ref coil
for MIDX RF out put from 4 TURN to 2 TURN
This will take out about 75MHz of Base line OSC.

DRAWING AFFECTED AND HOW (USE MARKER PRINTS AND ADDITIONAL SHEETS AS NEEDED)



Help considerable amount every time Perm. Change.

- L11-1210-30-0005 4TURN*
- 1210-30-0003 2TURN*

LA 006-004

ACTION			INITIALS	REASONS
PROJ. ENG.	APP	DISAPP		<i>Wrote ECD 4-28-81 AK.</i>
MECH ENG.	APP	DISAPP		
OTHER	APP	DISAPP		
OTHER	APP	DISAPP		
CH. ENG.	APP	DISAPP		