| ENGINEERING CHANGE NOTICE NO. 942 SHEET 1 OF 1 DATE RELEASED: 9/6/79 | | | | | | |
|--|-----|-----------------|--|-----|----------------|-------------------------|
| PROJ. ENG. A | | | RODUCTION AFFECTED ASSEMBLIES AFFECTED 2002A Sweep Time Assembly | | | |
| EXPLANATION OF CHANGE: | | | | | | |
| 1) Change diode on the Sweep Time sub assembly to make it easier to get 100 sec. sweep time. | | | | | | |
| 2) Get the diode on the correct parts list for assembly. | | | | | | |
| 3) Get correct ref des to avoid confusion. | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| PARTS TO BE ADDED | | | PARTS TO BE DELETED | | | PARTS LISTS AFFECTED |
| REF DES | QTY | SYSTEM PART NO. | REF DES | QTY | SYSTEM PART NO | |
| | | | CR15 | 1 | 4806-01-4004 | 1118-00-0018 |
| CR12 | 1 | 4807-01-0034 | | | | 1118-00-0038 |
| | | | | | • | |
| | | | | | • | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | • | |
| | | (| | 7 | 7 | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
