

Delta list: 2201 ProLock – 3G test set for mobile service

Revision history 1.10 → 1.20 (June 2009)

New Features
EDGE support
Multiple languages in manual mode supported
IP address is automatically recognized on start screen

Changes
Tor power level has been increased by 6 dB
Stability increased during band handovers on GSM
GPRS channel handover has been improved
Starting GSM after a GPRS test does not cause any problems anymore

Known Issues
USB connection can cause time outs from time to time. This will be fixed with the next release. So far Ethernet connection is recommended.

Revision history 1.00 → 1.10 (March 2009)

New Features
1489 Bluetooth Connectivity Test Option supported
Adjustable speech loopback delay for GSM supported
Loopback authentication can be switched off/on for WCDMA

Changes
Problems with BER measurement on GSM solved
Position of XY Shuttle is displayed in manual mode
Enhanced sensitivity on GSM
Minor changes in user interface
Easier firmware update procedure

Known Issues
Starting GSM after a GPRS test may cause problems. Doing GPRS after a GSM test is working well. The fix for this problem will come in the next firmware release.