





cos phi	L45	L45-O12	Besser:
1	0%	0%	2,60
0,5	1%	0%	3,09
0,2	2%	0%	3,55
0,1	3%	1%	3,76
0,05	6%	2%	3,87
0,02	16%	4%	3,95
0,01	32%	8%	3,97
0,005	64%	16%	3,99
0,002	160%	40%	3,99
0,001	320%	80%	4,00
0,0005	640%	160%	4,00
0,0002	1600%	400%	4,00
0,0001	3200%	800%	4,00



cos phi	L31	L31-O12	Besser:
1	0%	0%	3,55
0,5	1%	0%	4,73
0,2	2%	0%	6,19
0,1	3%	0%	6,96
0,05	6%	1%	7,44
0,02	16%	2%	7,76
0,01	32%	4%	7,88
0,005	64%	8%	7,94
0,002	160%	20%	7,98
0,001	320%	40%	7,99
0,0005	640%	80%	7,99
0,0002	1600%	200%	8,00
0,0001	3200%	400%	8,00



]

]