

**Direct Support Electrical System Test Set (DSESTS) 6625-01-120-0764**

**COLD WEATHER OPERATION**

***This abbreviated checklist is not to be used as a replacement for the -10 series Tech Manuals or any other PMCS guide***

Site and Shelter Requirements

1. The DSESTS test equipment will function properly in temperatures from 32 to 131 degrees Fahrenheit
2. The storage temperature range for the DSESTS test equipment is – 80 to 185 degrees Fahrenheit.