

General Purpose Interface Assembly (GPIA) 5998-01-382-7282
COLD WEATHER OPERATION

This abbreviated checklist is not to be used as a replacement for the -10 series Tech Manuals or any other PMCS guide

Site and Shelter Requirements

1. The DSESTS test equipment will function properly in temperatures from 32 to 131 degrees Fahrenheit
2. The storage temperature range for the DSESTS test equipment is – 80 to 185 degrees Fahrenheit.