# **\*TB 9-5210-213-50**

**DEPARTMENT OF THE ARMY TECHNICAL BULLETIN** 

# CALIBRATION PROCEDURE FOR PRECISION LEVEL STARRETT MODEL 199

Headquarters, Department of the Army, Washington, DC 23 May 2003

#### **REPORTING OF ERRORS AND RECOMMENDING IMPROVEMENTS**

You can improve this manual. If you find any mistakes or if you know of a way to improve these procedures, please let us know. Mail your letter, DA Form 2028 (Recommended Changes to Publications and Blank Forms), directly to: Commander, U.S. Army Aviation and Missile Command, ATTN: AMSAM-MMC-MA-NP, Redstone Arsenal, AL 35898-5000. A reply will be furnished to you. You may also provide DA Form 2028 information to AMCOM via e-mail, fax, or the World Wide Web. Our fax number is DSN 788-6546 or Commercial 256-842-6546. Our e-mail address is: <u>2028@redstone.army.mil</u>. Instructions for sending an electronic 2028 may be found at the back of this manual. For the World Wide Web, use https://amcom2028.redstone.army.mil.

Approved for public release; distribution is unlimited

			Paragraph	Page
SECTION	I.	IDENTIFICATION AND DESCRIPTION		-
		Test instrument identification	1	2
		Forms, records, and reports	2	2
		Calibration description	3	2
	II.	EQUIPMENT REQUIREMENTS		
		Equipment required	4	2
		Accessories required	5	2
	III.	CALIBRATION PROCESS		
		Preliminary instructions	6	3
		Equipment setup	7	3
		Adjustable Level Vial	8	3
		Final procedure	9	4

<sup>\*</sup>This bulletin supersedes TB 9-5210-213-50, dated 15 May 1987.

### **SECTION I IDENTIFICATION AND DESCRIPTION**

**1. Test Instrument Identification.** This bulletin provides instructions for the calibration of Precision Level, Starrett Model 199. The manufacturer's manual and Commercial Item Description A-A-50685 were used as the prime data sources in compiling these instructions. The equipment being calibrated will be referred to as the TI (test instrument) throughout this bulletin.

a. Model Variations. None.

**b. Time and Technique**. The time required for this calibration is approximately 1 hour, using the physical technique.

**2.** Forms, Records, and Reports. Forms, records, and reports required for calibration personnel at all levels are prescribed by TB 750-25.

**3.** Calibration Description. TI parameters and performance specifications which pertain to this calibration are listed in table 1.

Table 1. Calibration Description							
Test instrument parameters	Performance specifications						
Precision level	Range: 0.0015 inch per 12 inches						
	Sensitivity: .0005 inch per 12 inches						

Table 1 Calibration Deceminti

# SECTION II **EQUIPMENT REQUIREMENTS**

**4. Equipment Required.** Table 2 identifies the specific equipment to be used in this calibration procedure. This equipment is issued with Secondary Transfer Calibration Standards Set NSN 4931-00-621-7878. Alternate items may be used by the calibrating activity when the equipment listed in table 2 is not available. The items selected must be verified to perform satisfactorily prior to use and must bear evidence of current calibration. The equipment must meet or exceed the minimum use specifications listed in table 2.

5. Accessories Required. The accessories required for this calibration are common usage accessories issued as indicated in paragraph **4** above and are used in this calibration procedure.

 Table 2. Minimum Specifications of Equipment Required

N		linimum use	Manufacturer and model	
Common name	S	pecifications	(	part number)
SURFACE PLATE	Accurac	y: ±0.0001 in.	7900123	
	Grade A	Ā		

#### SECTION III CALIBRATION PROCESS

#### 6. Preliminary Instructions

**a**. The instructions outlined in paragraphs **6** and **7** are preparatory to the calibration process. Personnel should become familiar with the entire bulletin before beginning the calibration.

**b**. Items of equipment used in this procedure are referenced within the text by common name as listed in table 2.

**c**. Unless otherwise specified, verify the result of each test and, whenever the test requirement is not met, take corrective action before continuing with the calibration. Additional maintenance information is contained in the manufacturer's manual for this TI.

**d**. Unless otherwise specified, all controls and control settings refer to the TI.

### 7. Equipment Setup

**a**. Remove equipment from their cases.

**b**. Carefully examine all machined surfaces for nicks, burrs, and any other signs of damage and deburr as needed.

**c**. Ensure that all machined surfaces are clean.

#### 8. Adjustable Level Vial

#### NOTE

Allow bubble to settle 15 seconds before taking a reading.

#### NOTE

Make certain no one is propping or leaning on the surface plate.

#### a. Performance Check

(1) Place TI on surface plate and against a parallel bar that has been clamped to the clamping ledge of the surface plate, this will ensure repeatable observations.

(2) Note the reading, and rotate the TI  $180^{\circ}$ .

(3) If this reading is not the same magnitude and direction as the first reading perform  ${f b}$  below.

(4) If the two readings are the same magnitude and direction, then the surface plate is out of level. Bring the surface plate into a level condition by removing half the error as observed on the TI vial with the surface plate leveling screws. Rotate the TI 180° and again remove one half the error with the surface plate leveling screws. Repeat this technique till no further improvement can be seen.

#### TB 9-5210-213-50

(5) When the TI can be rotated  $180^{\circ}$  and there is no apparent change in the position of the bubble and it is in the center area of the vial, the TI is correctly adjusted.

# b. Adjustments

(1) Rotate the TI so that it indicates the greatest error in magnitude and remove the screw dust cover from over the main vial adjustment screw.

(2) Adjust the vial with this screw to remove one half the difference between the two readings. Again rotate the TI  $180^{\circ}$  and note the reading; then, rotate TI again and remove one half the difference with the vial adjustment screw. Repeat this technique until no further improvement can be seen then proceed to 8a(4) above.

# 9. Final Procedure.

- **a**. Replace dust cap over vial adjustment screw.
- **b**. Annotate and affix DA label/form in accordance with TB 750-25.

By Order of the Secretary of the Army:

ERIC K. SHINSEKI General, United States Army Chief of Staff

OFFICIAL:

Jul B. Huhn

JOEL B. HUDSON Administrative Assistant to the Secretary of the Army 0309202

To be distributed in accordance with STD IDS NO. RLC 1500, 2 January 2003, requirements for calibration procedure TB 9-.5210-213-50.

#### **THESE ARE THE INSTRUCTIONS FOR SENDING AN ELECTRONIC 2028**

The following format must be used if submitting an electronic 2028. The subject line must be exactly the same and all fields must be included; however, only the following fields are mandatory: 1, 3, 4, 5, 6, 7, 8, 9, 10, 13, 15, 16, 17, and 27.

From: "Whomever" <u>whomever@avma27.army.mil</u>

To: <u>2028@redstone.army.mil</u>

Subject: DA Form 2028

- 1. From: Joe Smith
- 2. Unit: Home
- 3. Address: 4300 Park
- 4. **City**: Hometown
- 5. St: MO
- 6. **Zip**: 77777
- 7. **Date Sent**: 19-Oct-93
- 8. **Pub No**: TB 9-6625-xxxx-35
- 9. **Pub Title**: Calibration Procedure for ...
- 10. **Publication Date**:
- 11. Change Number:
- 12. Submitted Rank: MSG
- 13. Sumitter Fname: Joe
- 14. Submitter Mname: T
- 15. Submitter Lname: Smith
- 16. Submitter Phone: (123) 123-1234
- 17. **Problem**: 1
- 18. Page: 2
- 19. Paragraph: 3
- 20 Line: 4
- 21. NSN: 5
- 22. Reference: 6
- 23. Figure : 7
- 24. Table: 8
- 25. Item: 9
- 26. Total: 123
- 27: **Text**:

This is the text for the problem below line 27.

## TB 9-5210-213-50